

Oil Field Environmental Incident Summary

Incident: 20150429055920 **Date/Time of Notice:** 04/29/2015 05:59

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: FBIR NELLIEOLDMOUSE 13X-13B

Field Name: HEART BUTTE

Well File #: 20632

Date Incident: 4/28/2015 **Time Incident:** 06:00

Facility ID Number:

County: DUNN

Twp: 148

Rng: 92

Sec: 13

Qtr:

Location Description:

Submitted By: Kaylan Dirkx

Received By:

Contact Person: Kaylan Dirkx
P.O Box 1589
Sidney, MT 59270

General Land Use: Pasture

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	9	Barrels	8	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None-spill was stopped upon discovery and was contained within the lined metal berm.

Areal Extent:

Potential Environmental Impacts:

None- spill was contained within the lined metal berm.

Action Taken or Planned:

Site glass will be repaired and impacted material will be removed and disposed at an approved facility.

Wastes Disposal Location: 8 bbls of oil were recovered and returned to the production tanks.
Impacted material within the lined metal berm will be disposed at
Chimney Butte

Agencies Involved:

Updates

Date: 4/29/2015 ***Status:*** Reviewed - Assigned to Other Agency

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to treater leak, remained on location within the diking according to the report. NDIC retains oversight.